Oil Field Environmental Incident Summary

Responsible Party: EMERALD OIL, INC
Well Operator: EMERALD OIL, INC
Well Name: EXCALIBUR 5-25-36H

Field Name: BOXCAR BUTTE Well File #: 25650

Date Incident:5/25/2016Time Incident:09:30Facility ID Number:County:MCKENZIETwp:149Rng:102Sec:25Qtr:

Location Description:

Submitted By: Scott Anderson Received By:

Contact Person: Scott Anderson

200 COLUMBINE ST, STE 500

DENVER, CO 80206

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

It is currently raining and heightens the risk of crude migrating off location.

Areal Extent:

Potential Environmental Impacts:

Topsoil, and possible surface water impacts.

Action Taken or Planned:

Vac trucks have already cleaned up release and there is no threat of fluid leaving location. The valve will be replaced.

Wastes Disposal Location: IHD

Agencies Involved:

Updates

Date: 5/27/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.